

2012
11/20
/80

PART NO.	CODE NO.	NUMBER OF CONTACT	DIMENSION OF CONNECTOR, LAND PATTERN, METAL MASK AND FFC/FPC DIMENSION OF DRAWING FOR PACKING												
			А	В	С	D	Е	F	G	Н	J	K	L	М	N
FH52-8(4)SB-1SH		4	8.3	3	4.57	6.7	6.1	6.1	4.5	8.6	11.5	24	_	29.4	25.4
FH52-10(5)SB-1SH		5	9.3	4	5.57	7.7	7.1	7.1	5.5	9.6	11.5	24	_	29.4	25.4
FH52-12(6)SB-1SH		6	10.3	5	6.57	8.7	8.1	8.1	6.5	10.6	11.5	24		29.4	25.4
FH52-16(8)SB-1SH		8	12.3	7	8.57	10.7	10.1	10.1	8.5	12.6	11.5	24		29.4	25.4
FH52-18(9)SB-1SH	/	9	13.3	8	9.57	11.7	11.1	11.1	9.5	13.6	11.5	24		29.4	25.4
FH52-20(10)SB-1SH		10	14.3	9	10.57	12.7	12.1	12.1	10.5	14.6	11.5	24		29.4	25.4
FH52-22(11)SB-1SH		11	15.3	10	11.57	13.7	13.1	13.1	11.5	15.6	11.5	24		29.4	25.4
FH52-24(12)SB-1SH		12	16.3	11	12.57	14.7	14.1	14.1	12.5	16.6	14.2	32	28.4	37.4	33.4
FH52-26(13)SB-1SH		13	17.3	12	13.57	15.7	15.1	15.1	13.5	17.6	14.2	32	28.4	37.4	33.4
FH52-28(14)SB-1SH		14	18.3	13	14.57	16.7	16.1	16.1	14.5	18.6	14.2	32	28.4	37.4	33.4
FH52-30(15)SB-1SH		15	19.3	14	15.57	17.7	17.1	17.1	15.5	19.6	14.2	32	28.4	37.4	33.4
FH52-32(16)SB-1SH		16	20.3	15	16.57	18.7	18.1	18.1	16.5	20.6	20.2	44	40.4	49.4	45.4
FH52-40(20)SB-1SH		20	24.3	19	20.57	22.7	22.1	22.1	20.5	24.6	20.2	44	40.4	49.4	45.4
FH52-50(25)SB-1SH		25	29.3	24	25.57	27.7	27.1	27.1	25.5	29.6	20.2	44	40.4	49.4	45.4
FH52-60(30)SB-1SH		30	34.3	29	30.57	32.7	32.1	32.1	30.5	34.6	26.2	56	52.4	61.4	57.4

™CONTACT POSITIONS WITHOUT CODE NUMBERS ARE CURRENTLY UNDER PLANNING. PLEASE CONTACT HIROSE FOR DETAILED INFORMATION ABOUT PRODUCT VARIATION.

> PART NO.
> CODE NO. EDC3-340560-00 FH52-*(*)SB-1SH CL580

FORM HC0011-5-8

This connector requires delicate and careful handling. Read through the instructions shown below and handle the connector properly. Each values indicating here are for reference and may differ from standard value.

LINSTRUCTIONS FOR MOUNTING ON THE BOARD!

♦ Warp of Board

Minimize warp of the board as much as possible. Lead co-planarity including reinforced metal fittings is 0.1 mm or less. Too much warp of the board may result in a soldering failure.

♦ Load to Connector

Do not apply a force of 1 N or more to the connector before mounting it on the board. Otherwise, the connector may be broken.

Do not insert the FFC or operate the connector before mounting it.

♦ Lord to Board


- ·Splitting a large board into several pieces
- ·Screwing the board

Avoid the handling described above so that no force is exerted on the board during the assembly process. Otherwise, the connector may become defective.

♦ Amount of Warp

The warp of a 100mm wide board should be 1 mm or less.

The warp of board suffers stress on connector and the connector may become defective.




ITNSTRUCTIONS ON INSERTING FEC/FPC AND CONNECTION!

♦ Use of the Actuator


Deformation of the terminal

1. Be very careful not to apply excessive force when releasing the actuator in the initial position.


If you use your nail or finger as shown below, the terminals may be deformed.



- 2. The actuator rotates around the rotational axis as shown below. Rotate the actuator.
- 3. The actuator will not open more than 110°. Do not apply any force backward beyond this point. Otherwise, the actuator may come off or break.



- 4. Move the actuator at approximately the center.
- 5. Do not pinch or pick the actuator to lift it as shown below. Otherwise, it may break. (Do not carry out any operation other than rotating the actuator as shown in 2 above.)




EDC3-340560-00 FH52-*(*)SB-1SH CL580


◆ Direction of Contacts This connector has contacts on the bottom. Thus, insert FFC/FPC with the exposed conductors face down.

♦ Inserting the FFC/FPC


1. Insert the FFC/FPC by about 10 degrees along the surface and at a right angle to the connector. Insert it properly to the very end.



- 2. Do not insert the FFC/FPC diagonally from above. If the FFC/FPC is inserted at a slant (incorrectly) as shown below in the FFC/FPC insertion process. the edge of the FFC/FPC may catch in the terminals, resulting in deformation of the terminals. The FFC/FPC may bend and patterns may break or the FFC may not insert completely. resulting in improper conduction.
 - ₩ Keep a sufficient FFC/FPC insertion space in the stage of the layout in order to avoid incorrect FFC/FPC insertion. Besides, it is not difficult to insert FFC/FPC correctly all the way to the end. Design the proper layout of parts.
 - ₩ Make adjustments with the FFC/FPC manufacturer for FFC/FPC bending perfomance and wire breakage



3. Do not rotate the actuator when FFC/FPC TAB is on right and left guides for positioning FFC/FPC. Make sure the position of FFC TAB and guides before rotate the actuator.



♦ Checking the Locking Condition


In the locked condition, make sure that the actuator is horizontal on the board surface. Do not apply excessive force to it near the 0° position of the actuator. Otherwise, the terminals may be deformed.

INSTRUCTIONS ON FFC/FPC LAYOUT AFTER CONNECTION!

♦ Load to FFC/FPC


Be very careful not to apply any force to the connector directly after inserting FFC/FPC. Otherwise, the connector may become unlocked or the FFC/FPC may break. In particular, design the FFC/FPC layout with care not to bend it sharply upward in a vertial direction near the insertion opening. Fix the FFC/FPC when loads are applied to it continuously.

Load: 0. 10 X n N MAX (n:number of contacts)



INSTRUCTIONS ON REMOVING FEC/FPC!

- ♦ Move the actuator at approximately the center.
- ♦ Release the actuator to remove the FFC/FPC. Remove the FFC/FPC by about 10 degrees along the surface.



IOTHER INSTRUCTIONS

♦ Instructions on Manual Soldering

Follow the instructions shown below when soldering the connector manually during repair work, etc.

- 1. Do not perform reflow soldering or manual soldering with the FFC inserted into the connector.
- 2. Do not heat the connector excessively. Be very careful not to let the soldering iron contact any parts other than connector leads. Otherwise, the connector may be deformed or melt.
- 3. Do not use excessive solder (or flux). If excessive solder (or flux) is used on the terminals, solder or flux may adhere to the contacts or rotating parts of the actuator, resulting in poor contact or a rotation failure of the actuator. Supplying excessive solder to the reinforcing bracket may hinder actuator rotation, resulting in breakage of the connector.



HS.	DRAWING NO.	EDC3-340560-00			
	PART NO.	FH52-*(*)SB-1SH	1		
		CODE NO.	CL580	\triangle	5/5
		7	8		

FORM HC0011-5-8 1