



Title of Change:	Packing Change for SOIC-8 MSL 1 products.																																																																						
Effective date:	20 December 2018																																																																						
Contact information:	Contact your local ON Semiconductor Sales Office or < Erik.Comparini@onsemi.com >																																																																						
Type of notification:	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.																																																																						
Change Category:	☐ Wafer Fab ☐ Assembly Change ☐ Test Change ☒ Other <u>Packing</u>																																																																						
Change Sub-Category(s): ☐ Manufacturing Site Addition ☐ Material Change ☐ Datasheet/Product Doc change ☐ Manufacturing Site Transfer ☐ Product specific change ☒ Shipping/Packaging/Marking ☐ Manufacturing Process Change ☐ Other: _____																																																																							
Sites Affected:	ON Semiconductor Sites: ON Carmona, Philippines ON Tarlac City, Philippines	External Foundry/Subcon Sites: ASE Kunshan GEM Greatek Stars Hana																																																																					
Description and Purpose: SOIC-8 MSL 1 products will be packed two reels per intermediate box in order to optimize dimensional shipping weight and reduce waste. There is no change to the form, fit or function of the product. There is no change in box size or box specification. Customers may continue to order single reel increments with no change in box size or packing. If customers order in multiples of two reels, the reels will be packed two reels per intermediate box.																																																																							
List of Affected Parts: <table border="0" style="width: 100%;"> <tbody> <tr> <td>NSS40300DDR2G</td> <td>FDS8817NZ</td> <td>FDS6673BZ</td> <td></td> </tr> <tr> <td>NSS40300MDR2G</td> <td>FDS8858CZ</td> <td>MC100LVEL11DR2G</td> <td>MC10ELT25DR2G</td> </tr> <tr> <td>NSS40301MDR2G</td> <td>FDS8870</td> <td>MC100LVEL16DR2G</td> <td>NTMD6N02R2G</td> </tr> <tr> <td>NSS40302PDR2G</td> <td>FDS8876</td> <td>FDS6930B</td> <td>MC10EP08DR2G</td> </tr> <tr> <td>FDFS2P753Z</td> <td>FDS8882</td> <td>FDS8880</td> <td>MC10EP11DR2G</td> </tr> <tr> <td>FDFS6N548</td> <td>FDS8896</td> <td>FDS9431A</td> <td>MC10EP32DR2G</td> </tr> <tr> <td>FDFS6N754</td> <td>FDS8928A</td> <td>FDS9926A</td> <td>NTMS4177PR2G</td> </tr> <tr> <td>FDS4410A</td> <td>FDS8958A</td> <td>NDS8425</td> <td>MC10EP33DR2G</td> </tr> <tr> <td>FDS4435A</td> <td>FDS8958B</td> <td>SI4532DY</td> <td>MC10EP51DR2G</td> </tr> <tr> <td>FDS4465</td> <td>FDS8960C</td> <td>MC100EL01DR2G</td> <td>MC10LVEP11DR2G</td> </tr> <tr> <td>FDS4501H</td> <td>FDS8978</td> <td>MC100EL07DR2G</td> <td>MC12026ADR2G</td> </tr> <tr> <td>FDS4935A</td> <td>FDS8978-F40</td> <td>MC100EL11DR2G</td> <td>MC12080DR2G</td> </tr> <tr> <td>FDS4935BZ</td> <td>FDS9400A</td> <td>MC100EL16DR2G</td> <td>MC12093DR2G</td> </tr> <tr> <td>FDS6294</td> <td>FDS9435A-NBAD008</td> <td>MC100EL32DR2G</td> <td>MCK12140DR2G</td> </tr> <tr> <td>FDS6298</td> <td>FDS9934C</td> <td>MC100EL58DR2G</td> <td>NB100ELT23LDR2G</td> </tr> <tr> <td>FDS6375</td> <td>FDS9953A</td> <td>MC100ELT22DR2G</td> <td>NB2304AI1DR2G</td> </tr> <tr> <td>FDS6570A</td> <td>NDS8434</td> <td>MC100ELT24DR2G</td> <td>NB2305AI1DR2G</td> </tr> </tbody> </table>				NSS40300DDR2G	FDS8817NZ	FDS6673BZ		NSS40300MDR2G	FDS8858CZ	MC100LVEL11DR2G	MC10ELT25DR2G	NSS40301MDR2G	FDS8870	MC100LVEL16DR2G	NTMD6N02R2G	NSS40302PDR2G	FDS8876	FDS6930B	MC10EP08DR2G	FDFS2P753Z	FDS8882	FDS8880	MC10EP11DR2G	FDFS6N548	FDS8896	FDS9431A	MC10EP32DR2G	FDFS6N754	FDS8928A	FDS9926A	NTMS4177PR2G	FDS4410A	FDS8958A	NDS8425	MC10EP33DR2G	FDS4435A	FDS8958B	SI4532DY	MC10EP51DR2G	FDS4465	FDS8960C	MC100EL01DR2G	MC10LVEP11DR2G	FDS4501H	FDS8978	MC100EL07DR2G	MC12026ADR2G	FDS4935A	FDS8978-F40	MC100EL11DR2G	MC12080DR2G	FDS4935BZ	FDS9400A	MC100EL16DR2G	MC12093DR2G	FDS6294	FDS9435A-NBAD008	MC100EL32DR2G	MCK12140DR2G	FDS6298	FDS9934C	MC100EL58DR2G	NB100ELT23LDR2G	FDS6375	FDS9953A	MC100ELT22DR2G	NB2304AI1DR2G	FDS6570A	NDS8434	MC100ELT24DR2G	NB2305AI1DR2G
NSS40300DDR2G	FDS8817NZ	FDS6673BZ																																																																					
NSS40300MDR2G	FDS8858CZ	MC100LVEL11DR2G	MC10ELT25DR2G																																																																				
NSS40301MDR2G	FDS8870	MC100LVEL16DR2G	NTMD6N02R2G																																																																				
NSS40302PDR2G	FDS8876	FDS6930B	MC10EP08DR2G																																																																				
FDFS2P753Z	FDS8882	FDS8880	MC10EP11DR2G																																																																				
FDFS6N548	FDS8896	FDS9431A	MC10EP32DR2G																																																																				
FDFS6N754	FDS8928A	FDS9926A	NTMS4177PR2G																																																																				
FDS4410A	FDS8958A	NDS8425	MC10EP33DR2G																																																																				
FDS4435A	FDS8958B	SI4532DY	MC10EP51DR2G																																																																				
FDS4465	FDS8960C	MC100EL01DR2G	MC10LVEP11DR2G																																																																				
FDS4501H	FDS8978	MC100EL07DR2G	MC12026ADR2G																																																																				
FDS4935A	FDS8978-F40	MC100EL11DR2G	MC12080DR2G																																																																				
FDS4935BZ	FDS9400A	MC100EL16DR2G	MC12093DR2G																																																																				
FDS6294	FDS9435A-NBAD008	MC100EL32DR2G	MCK12140DR2G																																																																				
FDS6298	FDS9934C	MC100EL58DR2G	NB100ELT23LDR2G																																																																				
FDS6375	FDS9953A	MC100ELT22DR2G	NB2304AI1DR2G																																																																				
FDS6570A	NDS8434	MC100ELT24DR2G	NB2305AI1DR2G																																																																				



FDS6574A	NDS9952A	MC100ELT25DR2G	NB2305AI1HDR2G
FDS6575	SI4435DY	MC100EP140DR2G	NB3M8302CDR2G
FDS6576	SI4542DY	MC100EP32DR2G	NB3N200SDR2G
FDS6612A	FIN1017MX	MC100EP51DR2G	NB3N201SDR2G
FDS6630A	FIN1027AMX	MC100EP52DR2G	NB3N206SDR2G
FDS6670A	FIN1028MX	MC100EPT20DR2G	NB3N3010BDR2G
FDS6670AS	FIN1101MX	NB2304AI2DR2G	NB3N502DR2G
FDS6675	FMS6141CSX	MC100EPT21DR2G	NB6L11DR2G
FDS6675BZ	FMS6143ACSX	MC100EPT22DR2G	NB6L16DR2G
FDS6676AS	FMS6143CSX	NB3L553DR2G	P2I2305NZG-08SR
FDS6679	FMS6363ACSX	MC100EPT23DR2G	P3I2005AG-08SR
FDS6679AZ	FMS6363CSX	MC100EPT24DR2G	P5P2305AF-1H08SR
FDS6680AS	FMS6404CSX	MC100EPT25DR2G	P5P23S05AF1H08SR
FDS6682	FMS6406CSX	MC100EPT26DR2G	PCS3P25811AG08SR
FDS6692A	FPF2303MX	MC100LVEL01DR2G	MMSF3P02HDR2G
FDS6699S	FDS6680A	MC100LVEL05DR2G	NTMD3P03R2G
FDS6875	FDS6680A-NBBI005A	NB3N551DR2G	NTMD4184PFR2G
FDS6890A	FDS6681Z	MC100LVEL32DR2G	NTMD4820NR2G
FDS6892A	FDS6690A	MC100LVEL33DR2G	NTMD4840NR2G
FDS6898AZ	FDS6690AS	MC100LVELT20DR2G	NTMD4N03R2G
FDS6900AS	FDS6898A	MC100LVELT22DR2G	NTMD6N03R2G
FDS6911	FDS6910	MC100LVELT23DR2G	NTMD6P02R2G
FDS6912	FDS6912A	MC100LVEP11DR2G	NTMS10P02R2G
FDS6930A	FDS6982AS	MC100LVEP16DR2G	NTMS4801NR2G
FDS6961A	FDS6986AS	MC10EL05DR2G	NTMS4802NR2G
FDS6975	FDS8878	MC10EL11DR2G	NTMS4807NR2G
FDS6984AS	FDS8884	MC10EL16DR2G	NTMS4816NR2G
FDS6990A	FDS8984	MC10EL31DR2G	NTMS4916NR2G
FDS6990AS	FDS9435A	MC10EL32DR2G	NTMS4920NR2G
FDS8433A	FDS9933A	MC10EL58DR2G	NTMS4937NR2G
FDS8672S	MC100ELT23DR2G	MC10EL89DR2G	NTMS4939NR2G
FDS8690	MC100EP11DR2G	MC10ELT20DR2G	NTMS7N03R2G
FDS8813NZ	FDS4435BZ	MC10ELT21DR2G	

NOTE:

Please be informed that there are Customer Specific parts impacted by this notice, thus MPN & CPN info will not be reflected in the parts list of this Generic document. Instead please click the link to the addendum copy provided in the email notification to see full list of affected products specific to your company.

Japanese translation of the notification starts here.
通知の日本語訳はここから始まります。

Note: *The Japanese version is for reference only. In case of any differences between the English and Japanese version, the English version shall control.*

注：日本語版は参照用です。英語版と日本語版の違いがある場合は、英語版が優先されます。



変更の件名:	SOIC-8 MSL 1 製品のパッキング変更。																																																																														
発効日:	20 December 2018																																																																														
連絡先情報:	現地のオン・セミコンダクター営業所または<Erik.Comparini@onsemi.com>にお問い合わせください。																																																																														
通知の種類:	本製品速報は通知目的のみのものです。オン・セミコンダクターは本製品速報の発行により本変更を実行します。																																																																														
変更カテゴリ:	☐ ウェハファブの変更 ☐ アセンブリの変更 ☐ 試験の変更 ☒ その他 <u>パッキング</u>																																																																														
変更サブカテゴリ:	☐ 製造拠点の追加 ☐ 材料の変更 ☐ データシート/製品資料の変更 ☐ 製造拠点の移転 ☐ 製品仕様の変更 ☒ 出荷/パッケージング/表記 ☐ 製造プロセスの変更 ☐ その他:																																																																														
影響を受ける拠点:	オン・セミコンダクター拠点: ON Carmona, Philippines ON Tarlac City, Philippines	外部ファウンドリまたは下請け業者拠点: ASE Kunshan GEM Greatek Stars Hana																																																																													
説明および目的: SOIC-8 MSL 1 製品の梱包を、輸送重量の最適化、廃棄物の削減のため、中間ボックスあたり 2 リールにします。製品の形状、適合性、機能に変更はありません。ボックスサイズなどボックスの仕様に変更はありません。顧客は、ボックスサイズや梱包の変更をともなわないシングルリールの注文もできますが、2 リールの倍数で注文した場合、中間ボックスあたり 2 リールが梱包されます。																																																																															
影響を受ける部品の一覧: <table border="1"> <tbody> <tr> <td>NSS40300DDR2G</td> <td>FDS8817NZ</td> <td>FDS6673BZ</td> <td></td> </tr> <tr> <td>NSS40300MDR2G</td> <td>FDS8858CZ</td> <td>MC100LVEL11DR2G</td> <td>MC10ELT25DR2G</td> </tr> <tr> <td>NSS40301MDR2G</td> <td>FDS8870</td> <td>MC100LVEL16DR2G</td> <td>NTMD6N02R2G</td> </tr> <tr> <td>NSS40302PDR2G</td> <td>FDS8876</td> <td>FDS6930B</td> <td>MC10EP08DR2G</td> </tr> <tr> <td>FDFS2P753Z</td> <td>FDS8882</td> <td>FDS8880</td> <td>MC10EP11DR2G</td> </tr> <tr> <td>FDFS6N548</td> <td>FDS8896</td> <td>FDS9431A</td> <td>MC10EP32DR2G</td> </tr> <tr> <td>FDFS6N754</td> <td>FDS8928A</td> <td>FDS9926A</td> <td>NTMS4177PR2G</td> </tr> <tr> <td>FDS4410A</td> <td>FDS8958A</td> <td>NDS8425</td> <td>MC10EP33DR2G</td> </tr> <tr> <td>FDS4435A</td> <td>FDS8958B</td> <td>SI4532DY</td> <td>MC10EP51DR2G</td> </tr> <tr> <td>FDS4465</td> <td>FDS8960C</td> <td>MC100EL01DR2G</td> <td>MC10LVEP11DR2G</td> </tr> <tr> <td>FDS4501H</td> <td>FDS8978</td> <td>MC100EL07DR2G</td> <td>MC12026ADR2G</td> </tr> <tr> <td>FDS4935A</td> <td>FDS8978-F40</td> <td>MC100EL11DR2G</td> <td>MC12080DR2G</td> </tr> <tr> <td>FDS4935BZ</td> <td>FDS9400A</td> <td>MC100EL16DR2G</td> <td>MC12093DR2G</td> </tr> <tr> <td>FDS6294</td> <td>FDS9435A-NBAD008</td> <td>MC100EL32DR2G</td> <td>MCK12140DR2G</td> </tr> <tr> <td>FDS6298</td> <td>FDS9934C</td> <td>MC100EL58DR2G</td> <td>NB100ELT23LDR2G</td> </tr> <tr> <td>FDS6375</td> <td>FDS9953A</td> <td>MC100ELT22DR2G</td> <td>NB2304AI1DR2G</td> </tr> <tr> <td>FDS6570A</td> <td>NDS8434</td> <td>MC100ELT24DR2G</td> <td>NB2305AI1DR2G</td> </tr> <tr> <td>FDS6574A</td> <td>NDS9952A</td> <td>MC100ELT25DR2G</td> <td>NB2305AI1HDR2G</td> </tr> <tr> <td>FDS6575</td> <td>SI4435DY</td> <td>MC100EP140DR2G</td> <td>NB3M8302CDR2G</td> </tr> </tbody> </table>				NSS40300DDR2G	FDS8817NZ	FDS6673BZ		NSS40300MDR2G	FDS8858CZ	MC100LVEL11DR2G	MC10ELT25DR2G	NSS40301MDR2G	FDS8870	MC100LVEL16DR2G	NTMD6N02R2G	NSS40302PDR2G	FDS8876	FDS6930B	MC10EP08DR2G	FDFS2P753Z	FDS8882	FDS8880	MC10EP11DR2G	FDFS6N548	FDS8896	FDS9431A	MC10EP32DR2G	FDFS6N754	FDS8928A	FDS9926A	NTMS4177PR2G	FDS4410A	FDS8958A	NDS8425	MC10EP33DR2G	FDS4435A	FDS8958B	SI4532DY	MC10EP51DR2G	FDS4465	FDS8960C	MC100EL01DR2G	MC10LVEP11DR2G	FDS4501H	FDS8978	MC100EL07DR2G	MC12026ADR2G	FDS4935A	FDS8978-F40	MC100EL11DR2G	MC12080DR2G	FDS4935BZ	FDS9400A	MC100EL16DR2G	MC12093DR2G	FDS6294	FDS9435A-NBAD008	MC100EL32DR2G	MCK12140DR2G	FDS6298	FDS9934C	MC100EL58DR2G	NB100ELT23LDR2G	FDS6375	FDS9953A	MC100ELT22DR2G	NB2304AI1DR2G	FDS6570A	NDS8434	MC100ELT24DR2G	NB2305AI1DR2G	FDS6574A	NDS9952A	MC100ELT25DR2G	NB2305AI1HDR2G	FDS6575	SI4435DY	MC100EP140DR2G	NB3M8302CDR2G
NSS40300DDR2G	FDS8817NZ	FDS6673BZ																																																																													
NSS40300MDR2G	FDS8858CZ	MC100LVEL11DR2G	MC10ELT25DR2G																																																																												
NSS40301MDR2G	FDS8870	MC100LVEL16DR2G	NTMD6N02R2G																																																																												
NSS40302PDR2G	FDS8876	FDS6930B	MC10EP08DR2G																																																																												
FDFS2P753Z	FDS8882	FDS8880	MC10EP11DR2G																																																																												
FDFS6N548	FDS8896	FDS9431A	MC10EP32DR2G																																																																												
FDFS6N754	FDS8928A	FDS9926A	NTMS4177PR2G																																																																												
FDS4410A	FDS8958A	NDS8425	MC10EP33DR2G																																																																												
FDS4435A	FDS8958B	SI4532DY	MC10EP51DR2G																																																																												
FDS4465	FDS8960C	MC100EL01DR2G	MC10LVEP11DR2G																																																																												
FDS4501H	FDS8978	MC100EL07DR2G	MC12026ADR2G																																																																												
FDS4935A	FDS8978-F40	MC100EL11DR2G	MC12080DR2G																																																																												
FDS4935BZ	FDS9400A	MC100EL16DR2G	MC12093DR2G																																																																												
FDS6294	FDS9435A-NBAD008	MC100EL32DR2G	MCK12140DR2G																																																																												
FDS6298	FDS9934C	MC100EL58DR2G	NB100ELT23LDR2G																																																																												
FDS6375	FDS9953A	MC100ELT22DR2G	NB2304AI1DR2G																																																																												
FDS6570A	NDS8434	MC100ELT24DR2G	NB2305AI1DR2G																																																																												
FDS6574A	NDS9952A	MC100ELT25DR2G	NB2305AI1HDR2G																																																																												
FDS6575	SI4435DY	MC100EP140DR2G	NB3M8302CDR2G																																																																												



FDS6576	SI4542DY	MC100EP32DR2G	NB3N200SDR2G
FDS6612A	FIN1017MX	MC100EP51DR2G	NB3N201SDR2G
FDS6630A	FIN1027AMX	MC100EP52DR2G	NB3N206SDR2G
FDS6670A	FIN1028MX	MC100EPT20DR2G	NB3N3010BDR2G
FDS6670AS	FIN1101MX	NB2304AI2DR2G	NB3N502DR2G
FDS6675	FMS6141CSX	MC100EPT21DR2G	NB6L11DR2G
FDS6675BZ	FMS6143ACSX	MC100EPT22DR2G	NB6L16DR2G
FDS6676AS	FMS6143CSX	NB3L553DR2G	P2I2305NZG-08SR
FDS6679	FMS6363ACSX	MC100EPT23DR2G	P3I2005AG-08SR
FDS6679AZ	FMS6363CSX	MC100EPT24DR2G	P5P2305AF-1H08SR
FDS6680AS	FMS6404CSX	MC100EPT25DR2G	P5P23S05AF1H08SR
FDS6682	FMS6406CSX	MC100EPT26DR2G	PCS3P25811AG08SR
FDS6692A	FPF2303MX	MC100LVEL01DR2G	MMSF3P02HDR2G
FDS6699S	FDS6680A	MC100LVEL05DR2G	NTMD3P03R2G
FDS6875	FDS6680A-NBBI005A	NB3N551DR2G	NTMD4184PFR2G
FDS6890A	FDS6681Z	MC100LVEL32DR2G	NTMD4820NR2G
FDS6892A	FDS6690A	MC100LVEL33DR2G	NTMD4840NR2G
FDS6898AZ	FDS6690AS	MC100LVELT20DR2G	NTMD4N03R2G
FDS6900AS	FDS6898A	MC100LVELT22DR2G	NTMD6N03R2G
FDS6911	FDS6910	MC100LVELT23DR2G	NTMD6P02R2G
FDS6912	FDS6912A	MC100LVEP11DR2G	NTMS10P02R2G
FDS6930A	FDS6982AS	MC100LVEP16DR2G	NTMS4801NR2G
FDS6961A	FDS6986AS	MC10EL05DR2G	NTMS4802NR2G
FDS6975	FDS8878	MC10EL11DR2G	NTMS4807NR2G
FDS6984AS	FDS8884	MC10EL16DR2G	NTMS4816NR2G
FDS6990A	FDS8984	MC10EL31DR2G	NTMS4916NR2G
FDS6990AS	FDS9435A	MC10EL32DR2G	NTMS4920NR2G
FDS8433A	FDS9933A	MC10EL58DR2G	NTMS4937NR2G
FDS8672S	MC100ELT23DR2G	MC10EL89DR2G	NTMS4939NR2G
FDS8690	MC100EP11DR2G	MC10ELT20DR2G	NTMS7N03R2G
FDS8813NZ	FDS4435BZ	MC10ELT21DR2G	

注:

本通知により影響を受ける顧客特定部品があり、よってMPN およびCPN 情報は本一般文書の部品リストに反映していないことにご留意ください。代わりに、特に御社に影響する製品の全リストを見るためには電子メール通知で提供される補遺コピーへのリンクをクリックしてください。