

RF Connectors☐ **TNC****AMP****1063929-1** ☐ **Active** [Active](#)[Not Reviewed for ELV/RoHS Compliance](#)**(Tyco Electronics P/N: 1063929-1)**[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information		
General Information	eCommerce	Related Part Information
☐ General Info	☐ Pricing	☐ Tooling
☐ Sales Info	☐ Product Availability	
☐ Assembly Subcontractors		

Searchable Features:

Brand:	AMP
Government/Industry Qualification:	No
RoHS/ELV Compliance:	Not reviewed for compliance
Product Type:	Connector
Gender:	Plug
Terminate To:	Coaxial Cable
Crimp Type:	Hex
Coaxial Cable Termination Type:	Solder/Clamp
Coaxial Cable Type (RG/U or Mfg.):	SF 142
Body Style:	Straight
Grade:	Commercial
Connector Impedance:	50

Other Properties:

Center Contact Plating:	Gold
Coupling Nut Material:	Stainless Steel
Center Contact Material:	Beryllium Copper per ASTM-B-194
Gasket Material:	Silicone Rubber
Retaining Ring Material:	Beryllium Copper
Frequency:	DC to 15 GHz

Panel Attachment:	No
Body Material:	Stainless Steel
Body Plating:	Passivated
Dielectric Material:	PTFE Thermoplastic
Weatherproof:	No
Solder Terminal:	Without

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

