


FIG-2 DRAWING FOR PACKING(AT 2000 pcs PACKING.)

THIS IS ONE EXAMPLE OF PACKING METHOD, AND IT MAY CHANGE WITHOUT ANY NOTICE, DEPENDING ON VOLUME.

1. STORE CONNECTORS IN A TRAY.

2. BAND TRAYS AS SHOWN BELOW.

3. STORE 2 UNITS OF BANDED TRAY INTO A CARTON BOX(K-1) (STORE A BOUNDARY PLATE ON TOP OF THE SURFACE, THEN CLOSE THE BOX BY STICKING GUMMED TAPE IN FOUR PARTS)



NOTES. 1 DIMENSIONS OF SMT RANGE AND CO-PLANARITY ARE AS SHOWN BEROW.

— +0.1 — 0 (DATUM) -0.1

- LOT No. SHALL BE INDICATED AT THE POSITION AS SHOWN.

  THIS PRODUCT IS TRAY PACKING, AND 100 CONNECTORS FOR EACH TRAY.
  MINNIMUM ORDER QUANTITY WILL BE 100 pcs PER UNIT.

  THE SHADED AREAS SHOW LOCATIONS OF EJECTOR PINS.

  PLATING

FORM HC0011-5-8 1

CONTACT AREA : GOLD 0.75 Mm MIN. READ AREA : GOLD 0.03 m MIN. UNDER PLATING: NICKEL 24m MIN.

ſ	HS.	DRAWING NO.	EDC-126145-30-00	
-		PART NO.	ZX80-B-5SA(30)	
		CODE NO.	CL242-0019-7-30	2/
_				

D