



Test Procedure for the NCP457FCT2GEVB Evaluation Board

1. Connect strap between IN and Vbias
2. Connect 3.2 V between IN and GND
3. Check $V_{out} = 0$
4. Set $EN = 2V$
5. Check $V_{out} = V_{in}$
6. Set $EN = 0V$
7. Check V_{out} decreases down to GND
8. Disconnect V_{in}