



w/ Stud	15P	M2.6*0.45	3-2394032-5	4-2394032-5
		4-40 UNC	3-2394032-4	4-2394032-4
	9P	M2.6*0.45	1-2394032-5	2-2394032-5
		4-40 UNC	1-2394032-4	2-2394032-4
	PINS	DESCRIPTION	REEL PACKING	TRAY PACKING

PRODUCT FAMILY TABLE									
DOCUMENT.		DWN —	 TE Connectivity						
		CHK —							
UNLESS SPECIFIED:		APVD —	NAME D-sub Header, Plug, SMT — —						
—		PRODUCT SPEC —							
0.25		—							
—		APPLICATION SPEC —							
±		—	SIZE	CAGE CODE	DRAWING NO			RESTRICTED TO	
		WEIGHT —	A2	00779	C-2394032			—	
CUSTOMER DRAWING					SCALE	1:1		SHEET	2 of 5
							REV	A	



RECOMMENDED P.C.B LAYOUT For 15 position
(COMPONENT SIDE)

RECOMMENDED PCB LAYOUT 1
(COMPONENT SIDE VIEW)

THIS DRAWING IS A CONTROLLED DOCUMENT

DWN	—
CHK	—
APVD	—




		TE Connectivity
NAME _____		

D-sub Header, Plug, SMT

SIZE	CAGE CODE	DRAWING NO	RESTRICTED TO	
A2	00779	C-2394032	—	
			SCALE	SHEET
			1:1	2 OF 5
			REV A	


9P			
	M2.6 * 0.45	1-2394032-6	2-2394032-6
PINS	DESCRIPTION	REEL PACKING	TRAY PACKING

REVISIONS					
P	LTR	DESCRIPTION	DATE	DWN	APVD
-	-	SEE SHEET 1	-	-	-




Cutaway view

PIN	W
9P	44.0±0.30
15P	56.0±0.30




Seal, pack, label.




Put reel into outer box,
pay attention to the unified label direction.

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN	-	TE Connectivity	
		CHK	-		
		APVD	-	NAME	
DIMENSIONS: mm		TOLERANCES, UNLESS OTHERWISE SPECIFIED:		D-sub Header, Plug, SMT	
		0 PLC ± -		-	
		1 PLC ± -		-	
		2 PLC ± 0.25		-	
		3 PLC ± -		-	
		4 PLC ± -		-	
		ANGLES ± -		-	
MATERIAL		FINISH		SIZE	RESTRICTED TO
-		-		A2	-
				CAGE CODE	
				00779	
				DRAWING NO	
				C=2394032	
				SCALE	
				1:1	
				SHEET	
				4 of 5	
				REV	
				A	

REVISIONS					
P	LTR	DESCRIPTION	DATE	DWN	APVD
-	-	SEE SHEET 1	-	-	-





Product piping diagram





No. 1

put the product into the tray





No. 2

Cover the tray





No. 3

Label on top left corner of tray




No. 4

the top and bottom of each put a piece of paper board,




PE bag



No. 5

A waterproof PE bag should be set inside the carton, and then the tray should be put into the carton Sealed with a bag of desiccant.



No. 6

Seal and label on the top left corner of the carton side

Explain:
1. Put the product into the tray as shown in the figure
2. Pay attention to the consistency of label style position and direction;

THIS DRAWING IS A CONTROLLED DOCUMENT.		DWN	-	TE Connectivity			
		CHK	-				
DIMENSIONS:		APVD	-	NAME			
mm		PRODUCT SPEC	-	D-sub Header, Plug, SMT			
		APPLICATION SPEC	-				
		WEIGHT	-				
MATERIAL		FINISH	-	SIZE	CAGE CODE	DRAWING NO	RESTRICTED TO
				A2	00779	C-2394032	-
		CUSTOMER DRAWING		SCALE	1:1	SHEET	5 of 5
						REV	A