

N° 027/06

Change from Ink to Laser Marking for P/PG-TQFP / MQFP/ LQFP/ FQFP - Packages at subcon ASE

Objective: Due to process standardization product marking will be changed from ink to laser marking

Application: See affected product list 1_cip02706

Background: Laser marking will be introduced as the standard marking procedure at our subcon ASE, Taiwan

Realization:

Old:



Ink Marking

New:



Laser Marking

Time schedule: Effective from July 2006 onwards

If you have questions contact your local Sales office, please



INFORMATION NOTE

Affected Product list 1_cip02706

ADM3120PX-AB-T-2	ADM6996LH-AC-T-1	AN983BX-BG-T-V1
ADM5120P-AB-T-2	ADM6996LHX-AC-T-1	AN983BX-BG-T-V3
ADM5120PS-AB-T-2	ADM6996M-AC-T-1	AN983X-AH-T-21
ADM5120PSX-AB-T2	ADM6996M-AD-T-1	AN983X-AH-T-22
ADM5120PX-AB-T-2	ADM6996MX-AC-T-1	AN985B-BG-T-V1
ADM6918-AB-T-1	ADM6996MX-AD-T-1	AN985BG-BG-T-V1
ADM6918X-AB-T-1	ADM6996X-A2-T-1	AN985BX-BG-T-V1
ADM6926-AB-T-1	ADM6999-A2-T-1	AT8992-A2-T-1
ADM6926X-AB-T-1	ADM6999G-A2-T-1	AT8992M-A2-T-1
ADM6992-AD-T-1	ADM6999GX-A2-T-1	AT8993-A2-T-1
ADM6992C-AB-T-1	ADM6999U-A2-T-1	DM8608BFP-AD-T-1
ADM6992CX-AB-T-1	ADM6999UX-A2-T-1	PEB 3304 HL V1.3.
ADM6992F-AB-T-1	ADM6999X-A2-T-1	PEB 3304 HL V1.4
ADM6992FX-AB-T-1	ADM7001-AC-R-1	PEB 3314 HL V1.4
ADM6992K-AB-T-1	ADM7001-AC-T-1	PEB 3320 HL V1.4
ADM6992KX-AB-T-1	ADM7001X-AC-R-1	PEB 3322 HL V1.4
ADM6992SX-AB-T-1	ADM7001X-AC-T-1	PEB 3322 HL V1.4 PB
ADM6992X-AD-T-1	ADM7008-A3-T-1	PEB 3324 HL V1.4
ADM6993-AD-T-1	ADM7008-A3-T-2	PEB 3324 HL V1.4 PE
ADM6993F-AD-T-1	ADM7008X-A3-T-1	PEB 3394 HL V1.4
ADM6993FX-AD-T-1	ADM8262-AC-T-1	PEB 3394 HL V1.6
ADM6993X-AD-T-1	ADM8262X-AC-T-1	PEF 3304 HL V2.1
ADM6995LC-AC-T-1	ADM8266A21	PEF 3314 HL V2.1
ADM6995LC-AD-T-1	ADM8266MA21	PEF 3314 HL V2.2
ADM6995LCX-AC-T-1	ADM8511-CC-T-1	PEF 3394 HL V2.1
ADM6995LCX-AD-T-1	ADM8511X-CC-T-1	PEF 3394 HL V2.2
ADM6996-A2-T-1	ADM8513-AD-T-1	SAF-TC1161-128F66HL AA
ADM6996FC-AC-T-1	ADM8513X-AD-T-1	SAF-TC1162-128F66HL AA
ADM6996FC-AD-T-1	ADM8515-AC-T-1	SAF-TC1163-128F80HL AA
ADM6996FCX-AC-T-1	ADM8515X-AC-T-1	SAF-TC1164-128F80HL AA
ADM6996FCX-AD-R-1	ADM8628-AA-T-1	SAF-TC1165-192F80HL AA
ADM6996FCX-AD-T-1	ADM8628-AB-T-1	SAF-TC1166-192F80HL AA
ADM6996FH-AC-T-1	AN983-AH-T-21	SAK-TC1762-128F66HL AA
ADM6996FHX-AC-T-1	AN983-AH-T-22	SAK-TC1766-192F80HL BB
ADM6996HX-AD-T-1	AN983B-BG-T-V1	SAK-TC1766M-192F80HL BB
ADM6996I-AC-T-1	AN983B-BG-T-V2	
ADM6996I-AD-T-1	AN983B-BG-T-V3	
ADM6996IX-AC-T-1	AN983B-BG-T-V4	
ADM6996IX-AD-T-1	AN983B-BG-T-V5	
ADM6996LC-AC-R-1	AN983B-BG-T-V6	
ADM6996LC-AC-T-1	AN983B-BG-T-V7	
ADM6996LC-AD-T-1	AN983B-BG-T-V8	
ADM6996LCX-AC-R-1	AN983B-BG-T-V9	
ADM6996LCX-AC-T-1	AN983BL-BG-T-V1	
ADM6996LCX-AD-R-1	AN983BLX-BG-T-V1	
ADM6996LCX-AD-T-1	AN983BX-BG-R-V1	