

RF Connectors**SMA/QMA****AMP** **1086723-1** **Active** [Active](#)[Not Reviewed for ELV/RoHS Compliance](#)**(Tyco Electronics P/N: 1086723-1)**[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information

General Information	eCommerce	Related Part Information
General Info Sales Info Assembly Subcontractors	Pricing Product Availability	Tooling

Searchable Features:

Brand:	AMP
Government/Industry Qualification:	Yes
Government/Industry Part Number:	M39012/56-3602
RoHS/ELV Compliance:	Not reviewed for compliance
Lead Free Solder Process:	Not reviewed for lead free solder process
Product Type:	Connector
Gender:	Plug
Terminate To:	Coaxial Cable
Coaxial Cable Termination Type:	Crimp
Crimp Type:	Compression

Other Properties:

Military Category:	D
Center Contact Material:	Beryllium Copper, Copper Alloy
Center Contact Plating:	Gold
Frequency:	DC to 12.4 GHz
Dielectric Material:	TFE Fluorocarbon
Coupling Nut Material:	Stainless Steel
Gasket Material:	Silicone Rubber
Ferrule Material:	Copper, Brass

Coaxial Cable Type (RG/U or Mfg.):	142, 400
Body Style:	Right Angle
Panel Attachment:	No
Length (mm [in]):	34.93 [1.375]
Body Material:	Stainless Steel
Body Finish:	Passivated
Center Contact:	With
Retractable Collar:	Without
Safety Wire Holes:	Without

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

